

7/02/08/8

Xcel Energy - Jayma + John
Rebs

Leaving Yard reclaimed
left pile of dirt landowner wanted

Xcel brought development
project

County Roads signed off
State on Hwy 9

16 ft Radius on the pad

Spray weeds Spring & Fall
oil-grade every year
dress roads

recently sprayed at time of inspection
Concrete substituted Roads
in under main

Can has ~~Shaded~~ ground
Shaded

County had Xcel put up signs
"Mill blocks road"

Courtesy Windfarm ~~2017~~

pt 548 - turbine 100 August 30, 2017

can around pad

PP 101-0038-3

PP 519 - BMPS PD 247

Culvert plugged up
- by hand

Are monitoring area - change out
as for area - stabilize area
- hill uses cat for Road

pt 550 ^{low} ~~low~~ crossing - concrete
low area

PP 9
qu

turbine S9

PT 551
- Box - Cement Blocks

PP-18
ant

PS 52 - Substation - Culvert
= mud washed out - Street the
Area

Pt 553 - Plowed lines

by Substation

PP 27

962

Pt 554 - Seed w/ seed mix

Some weeds

PP 33

968

Reclaimed area

Pt 555 - had silt fences in this area.

turning - wetlands near

PP 41

976

- Crop near access Road

Pt 556 - CRP Land

had low weeds crossing it w/

PP 46

981

near it

Pt 557 - Road had been reclaimed

needed to order it for equipment

PP 49

988

Pt 558 - Declined Area by w/

PP 52

981

is monitoring it
from widening Road for equip

Pt 559 - Reclaimed Area

PP 56 - Farmers

991

Wanted 20 Piles left